



All T092 transistors are MPSA42 Please note, 5 transistors in raw marking is wrong, c and e has to be switched over